

HISTORIC RESOURCES INVENTORY—BUILDINGS AND STRUCTURES
Please send completed form to: State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2 nd Floor, Hartford, CT 06103 *Note: Please attach any additional or expanded information on a separate sheet.
GENERAL INFORMATION
Building Name (Common)
Building Name (Historic) Culbro Tobacco Division Farm #4
Street Address or Location 1503 Hopmeadow Street
Town/City: Simsbury Village Hoskins Station County: Hartford
Owner(s) River Bend Associates, Inc.
PROPERTY INFORMATION
Present Use Vacant
Historic Use Tobacco barn
Accessibility to Public: Exterior visible from public road? Xes
Interior accessible? Yes No If yes, explain
Style of building Vernacular Date of Construction c. 1920s
Materials (Indicate use or location when appropriate):
Clapboard Asbestos Siding Brick Wood Shingle Asphalt Siding
Fieldstone Board & Batten Stucco Cobblestone Aluminum Siding Concrete (Type) Cut Stone (Type) Other: Horizontal barn board
Concrete (Type) Cut Stone (Type) Other: Horizontal barn board)
Wood Frame Post & Beam Balloon Load-bearing Masonry Structural iron or steel
Other
Roof (<i>Type</i>)
Gable Flat Mansard Monitor Sawtooth
Gambrel Shed Hip Round Other —
(Material)
Wood Shingle Roll Asphalt Tin Slate Asphalt Shingle
Built up Tile Other
Number of Stories: <u>1</u> Approximate Dimensions n/a
Structural Condition:
Exterior Condition: Excellent Good Fair Deteriorated
Alterations? Yes No If yes, explain:
FOR OFFICE USE Town # Site UTM
District S NR, Specify: Actual Potential

Historic Resource Inventory, p. 2				p. 2	
PROPERTY I	VFORMATION	(CONT′D)			
Related outbuildings or landscape features:					
🔀 Barns	Shed	Garage	Carriage House	Shop	Garden
Other landscape features or buildings:					
Surrounding Environment:					
🛛 Open land	Woodland	Residential	Commercial	Industrial	Rural
High building density Scattered buildings visible from site					

• Interrelationship of building and surroundings:

A group of five tobacco sheds, lined up end to end, south to north, on the west side of Route 10. The buildings are on a slight rise, hard on the road, to the northeast of the International Skating Center. The northernmost barn is angled to the southeast. The grouping also includes a small bank barn between barn 3 and barn 4. Small shopping center across the street.

• Other notable features of building or site (Interior and/or Exterior)

These five barns have a similar design: an elongated peak-roofed building with its gable ends to the north and south; wagon entries in the gables. The venting system is the horizontal-board type operated with vertical hinges. Narrow vents cap the roof ridges, running almost the full length of the building but stopping just short of the gables. The north is nearly double the length of its four neighbors. Traces of exterior whitewash.

A	rcl	hit	tec	ct

Builder _____

Historical or Architectural Importance:

These abandoned tobacco sheds-built between two former towpaths on the Farmington Canal-are noteworthy for their horizontal-board ventilation system, a design typical of the 1920s barns used throughout town when the shade business was booming. This grouping was erected on what were known as the Ketchin Lots by the Ketchin Tobacco Corp, and was then sold or leased to the A.T. Pattison plantation. Sometime around the 1940s, the barns were acquired from the Pattison estate by Cullman Brothers and became part of that company's Farm #4, which also included operations on Wolcott Road.

• Sources:

Town of Simsbury Tax Assessor Records Information from Bill Walsh

Photographer:	Rachel	Carlev Date:	12/12

View: From the northeast and southwest Negative on file

Name: Rachel Carley Date: 1/13

Organization: Preservation Consultant 10 Camp Dutton Road Litchfield, CT 06759

• Subsequent field evaluations:



Threats to building or site:

None known	
Deterioration	

Highways	
Zoning	

 Vandalism
 Commercial
 Developers
 Renewal
 Private

 Other
 Explanation